

Report 14/2656

January 3rd, 2014

Page 1/1

Customer: Glen Dimplex Australasia Ltd
PO Box 58 473
Botany
AUCKLAND 2163

P197715

Accreditation

Laboratory Registration Number 395



This laboratory is accredited by International Accreditation New Zealand (IANZ). The tests reported herein have been performed in accordance with the terms of our accreditation. This accreditation does not extend to any opinions or any interpretations of test results contained in this report.



IANZ has a Mutual Recognition Arrangement (MRA) with the National Association of Testing Authorities (NATA), Australia, such that both organizations recognize accreditations by IANZ and NATA as being equivalent. Users of test reports are recommended to accept test reports in the name of either accrediting body.

Compliance Certificate

Appliance	Masport Mackenzie R10000 (Softwood) Freestanding Wood Burring Heater
Test Standard	AS/NZS 2918:2001 Appendix B
Full Report	13/2652. The full report contains information on the test methods, details of the appliance tested, the installation and the results of the test
Flue System	150 mm Flue with 5 sided double flue shield and deflector
Ceiling Plate	505 x 505 mm square polished stainless steel ceiling plate with 179 mm hole offset from the ceiling surface by 12 mm
Floor Protector	Tested without floor protector present. The minimum requirements of AS/NZS 2918:2001 clause 3.3.2 apply
Minimum Clearances	Side: 400 mm Rear: 150 mm Corner: 160 mm



This report:

Prepared by: G. Looman

Approved by: W. S. Webley

16/07/2014

Release Date

This report relates only to the product sample tested. Any modifications to the product may invalidate the compliance results. This report must not be reproduced except in full. Results are based on material and information supplied by the client. Applied Research Services Ltd shall not be liable in respect of any loss or damage (including consequential loss or damage) resulting from the use of reports prepared by them.